

EA-AMP-HYB-2D-X000 HYBRID AMPLIFIER

FIRMWARE RELEASE 03/20/2022

Model	Main Firmware
EA-AMP-HYB-2D-1000	8.04 -> 9.00

important: This firmware update requires a two-step update process. Both steps must be completed for a successful update. [Click here for instructions.](#)

Changes in This release**Improvements**

- Performance updates including higher output
- General bug fixes

FIRMWARE RELEASE 01/21/2022

Model	Main Firmware
EA-AMP-HYB-2D-2000	5.03 -> 6.00

important: This firmware update requires a two-step update process. Both steps must be completed for a successful update. [Click here for instructions.](#)

FIRMWARE RELEASE 12/02/2021

Model	Main Firmware
EA-AMP-HYB-2D-1000	8.00 -> 8.04

important: This firmware update requires a two-step update process. Both steps must be completed for a successful update. [Click here for instructions.](#)

Changes in This release

Enhances reliability with general bug fixes.

FIRMWARE RELEASE 04/13/2021

Model	Main Firmware
EA-AMP-HYB-2D-1000	8.00 -> 8.03
EA-AMP-HYB-2D-2000	5.00 -> 5.03

important: This firmware update requires a two-step update process. Both steps must be completed for a successful update. [Click here for instructions.](#)

Changes in This release**Improvements**

- Added webconnect from OvrC.
- Added front panel lockout to prevent customer changes to amplifier settings
- FW upgrade process has been optimized so future updates share one firmware file for both the 1000 and 2000 models
- Fixed SDDP flooding issue which caused amplifier and network slowdowns
- Future MAC OS firmware upgrade issues resolved
- Control system (telnet) password now syncs with web UI password

FIRMWARE RELEASE 09/03/2019

Model	Main Firmware
EA-AMP-HYB-2D-1000	6.12
EA-AMP-HYB-2D-2000	3.12

Changes in This release

Improvements

- Updated user accounts and user access to meet California's new IoT security legislation.
- Updated volume ramping curve for improved performance for units connected to a C4 system.
- Resolved an OvrC drop off issue, the amp would disconnect then would not automatically reconnect.

FIRMWARE RELEASE 09/03/2019

Model	Main Firmware
EA-AMP-HYB-2D-1000	5.10

Changes in This release

Improvements

- Added Save/Load Preset Feature
- Added Web UI firmware update Feature
- Made UI color optimizations
- Fixed iOS repeat logout issue
- Fixed wrong password entry/lock out issue

FIRMWARE RELEASE 05/20/2019

Model	Main Firmware
EA-AMP-HYB-2D-1000	4.02

Changes in This release

Improvements

- Speaker profile Y-Ch1 changed to Mono CH1 + Ch2
- Fixed issue where 12V trigger unable to power down during "light" power mode
- Extended digital certificates validity date

FIRMWARE RELEASE 04/03/2019

Model	Main Firmware
EA-AMP-HYB-2D-1000	3.00

Changes in This release

Improvements

- This is release firmware

TECHNICAL SUPPORT

For chat and telephone, visit ctrl4.co/techsupport • Email: TechSupport@SnapOne.com
Visit ctrl4.co/tc for discussions, instructional videos, news, and more.