Pro App v7.2.0.5 Release Notes

Release Details

Release Date	2022/12/15
Firmware Version	7.2.0.5
Product SKUs Affected	**Araknis x10 Series Routers Host Versions:** 1.2.16 and 1.2.23

Fixes

- Fixes an issue with upgradability from firmware version 1.2.16 onwards.

Pro App v7.2.0 Release Notes

Release Details

Release Date	2022/11/17
Firmware Version	7.2.0
Product SKUs Affected	**EA Controllers CA Controllers CORE Controllers OvrC-300 and 100 Hubs X10 Routers (110, 110W, 310) Pakedge Routers (RK-1, WR-1, RT-3100) NK-1 NX-1 Invision App**

Fixes

- Fixed data storage location in Pakedge WR-1. Persistent data for OvrC Pro was not being properly stored.

Enhancements

- Added periodic service boundaries for an upcoming feature release
- Updated UI and device access for improved cybersecurity
- Modified SDDP client and server features to support multiple network interfaces
- Added SDDP listener for Araknis X20 routers
- Added additional logging data for changing environments, debugging discovered devices and for Control4 controllers

Pro App v7.1.0 Release Notes

Release Details

Release Date	2022/10/20
Firmware Version	7.1.0
Product SKUs Affected	**EA Controllers** **CA Controllers** **CORE Controllers** **OvrC-300 and 100 Hubs** **X10 Routers (110, 110W, 310)** **Pakedge Routers (RK-1, WR-1, RT-3100)** **NK-1** **NX-1 Invision App**

Fixes

- Fix to accept x.x.x.254 addresses for static IP. Previously, this was not accepted by the OvrC Pro agent

Enhancements

- Support for 2022 Denon ([Learn More](#)) and Marantz AVRs ([Learn More](#)), pre-amps, and amplifiers
- Support for Sony projectors [Learn More](#)

Pro App v7.0 Release Notes

Release Details

Release Date	2022/09/22
Firmware Version	7.0
Product SKUs Affected	**EA Controllers** **CA Controllers** **CORE Controllers** **OvrC-300 and 100 Hubs** **X10 Routers (110, 110W, 310)** **Pakedge Routers (RK-1, WR-1, RT-3100)** **NK-1** **NX-1 Invision App**

Fixes

- Minor bug fixes and cosmetic improvements

Enhancements

- Third-party integration with Sony AVRs, sound bars, and line array speakers. (See supported models)
  - Services include adding the ability to turn zones on or off, mute zones, and perform firmware updates from OvrC
  - For more information, see this Knowledge Base article:
    https://tech.control4.com/s/article/Improvements-made-to-OvrC-and-OvrC-Pro
- Improved device discovery of Sony Bravia TVs that are wirelessly connected to the network

Pro App v6.4.0.9 Release Notes

Release Details

Release Date	2022/07/28
Firmware Version	6.4.0.9
Product SKUs Affected	**EA Controllers** **CA Controllers** **CORE Controllers** **OvrC-300 and 100 Hubs** **X10 Routers (110, 110W, 310)** **NX-1 Invision App**

Fixes

- Fixed an EA/CA controllers timing issue when booting the OvrC agent due to an incorrect reference MAC being pulled at boot.
- Fixed the CORE controller port duplex reading on the Ethernet port.
- Fixed the CORE controllers ST/SN reference on beta units that did not have the ST flashed to them.
- Fixed the controllers not showing online in OvrC due to incorrect interface binding.
- Fixed the CORE controllers method to WebConnect.

Enhancements

- Added OS version support on the Control4 controller running OS 3.2.2 or higher.
- Improved the connectivity of OvrC-enabled devices.
- Improved the SDDP discovery for 3rd party products.
- Improved the reliability of WebConnect when connecting to Araknis 110/310 routers.
- Improved the buffer and added efficient logging for Control4 mobile connections.

Pro App v6.4.0.3 Release Notes

Release Details

Release Date	2022/05/05
Firmware Version	6.4.0.3
Product SKUs Affected	**EA Controllers** **CA Controllers**

For all other OvrC Pro devices, **click here** to see their Pro App release notes.

Fixes

- Improved the timing of the Pro agent startup. This issue was identified where a Control4 controller showed a different MAC address in OvrC than what was on the device.

Enhancements

- Improved Control4 mobile app connection times.
- Controllers with multiple network interfaces (Ethernet and wireless) now appear as a single device. Both MAC addresses can be seen under the **Device Details**.

Pro App v6.3.0.6 Release Notes

Release Details

Release Date	2022/04/07
Firmware Version	6.3.0.6
Product SKUs Affected	**OVRC-300-PRO Host Device Version:** 5.1.0.6 **OVRC-100-HUB Host Device Version:** 5.1.0.8 **AN-310-RT-4L2W Host Device Version:** 1.1.66 **AN-110-RT-2L1W Host Device Version:** 1.0.88 **AN-110-RT-2L1W-WIFI Host Device Version:** 1.0.88 **RT-3100 Host Device Version:** 2.00.2.100632 **RK-1 Host Device Version:** 2.00.2.100853 **WR-1 Host Device Version:** 2.00.1.100321 **NK-1 Host Device Version:** 2.00.0.100267 **Pakedge NX-1** **Ihiji APP-750** **Ihiji APP-2000** **Ihiji APP-2100** **Ihiji APP-2000-UK** **Ihiji APP-2100-UK**

Enhancements

- Added ability for Pakedge devices to update the pro application without a reboot of the device.
- Updated the Hub Environment page to improve environment switching between dev/beta/prod.
- Fixed issue with webconnect wherein a user session would end quickly and abruptly due to cookie size limitations.

Pro App v6.3.0.4 Release Notes

Release Details

Release Date	2021/12/16
Firmware Version	6.3.0.4
Product SKUs Affected	**OVRC-300-PRO Host Device Version:** 5.1.0.6 **OVRC-100-HUB Host Device Version:** 5.1.0.8 **AN-310-RT-4L2W Host Device Version:** 1.1.66 **AN-110-RT-2L1W Host Device Version:** 1.0.88 **AN-110-RT-2L1W-WIFI Host Device Version:** 1.0.88 **RT-3100 Host Device Version:** 2.00.1.100626 **RK-1 Host Device Version:** 2.00.1.100848 **WR-1 Host Device Version:** 2.00.1 **NK-1 Host Device Version:** 2.00.0.100267 **EA Controllers Host Device Version:** 1.0.0.4 **CA Controllers Host Device Version:** 1.0.0.4

Enhancements

- Improved the accuracy of Control4 controller memory usage.
- Added VLAN configuration and scanning for locations where a Control4 controller is the OvrC Pro host.
- Allow for multiple attempts at updating Pakedge APs that are running firmware v1.xx firmware.
- Allow for dynamic device port when using WebConnect via OvrC. No longer hard coded to 80.
- Added synchronization of the monitoring bell between the OvrC server and OvrC Pro host.
- Improved WebConnect for protocols that require SSL where a Control4 controller is the OvrC Pro host.
- Changed health monitor logic to not ping a device that ARPing found the wrong MAC address for.
- Increased worker thread count to help run faster scans on hardware that supports it.
- Added SNMP support for Access Networks/Ruckus switches and changed the logic to identify matching manufacturers.
- Added SDDP listener to non-Control4 OvrC Pro agents for improved device naming.
- Fixed timestamps on OvrC Pro hosts running on Control4 controllers.

Pro App v6.2.1.7 Release Notes

Release Details

Release Date	2021/06/03
Firmware Version	6.2.1.7
Product SKUs Affected	**OVRC-300-PRO Host Device Version:** 5.1.0.6 **OVRC-100-HUB Host Device Version:** 5.1.0.6 **AN-310-RT-4L2W Host Device Version:** 1.1.64 **AN-110-RT-2L1W Host Device Version:** 1.0.86 **AN-110-RT-2L1W-WIFI Host Device Version:** 1.0.86 **RT-3100 Host Device Version:** 2.00.1.100626 **RK-1 Host Device Version:** 2.00.1.100848 **WR-1 Host Device Version:** 2.00.1 **NK-1 Host Device Version:** 2.00.0.100267 **EA Controllers Host Device Version:** 1.0.0.4 **CA Controllers Host Device Version:** 1.0.0.4

Enhancements

- Added Pakedge protocol to assist with migration of Pakedge devices to their respective firmware for OvrC-enablement.
- Improved handling of HTTPS on local UI of OvrC Pro devices.
- Improved Doorbird protocol from reporting non-Doorbird devices.
- Fixed issue with 3rd party devices falling offline on some customer sites in the field. For more details, see our **blog post**.

Pro App v6.2.0.5 Release Notes

Release Details

Release Date	2021/04/08
Firmware Version	6.2.0.5
Product SKUs Affected	**OVRC-300-PRO Host Device Version:** 5.1.0.2 **OVRC-100-HUB Host Device Version:** 5.1.0.4 **AN-310-RT-4L2W Host Device Version:** 1.1.64 **RT-3100 Host Device Version:** 2.00.1.100626 **RK-1 Host Device Version:** 2.00.1.100848 **NK-1 Host Device Version:** 2.00.0.100267

Enhancements

- Added a secondary check for third party devices to increase accuracy of device connection status.
- Updated HTTPS SSL method from SSLv2.3 to TLSv1.2.
- Updated hostname as device name for Denon, Marantz, and Yamaha devices.
- Updated Device Discovery, Health Monitor, and Internet Test services to be disabled by default on newly deployed OvrC Pro devices.

Resolved Issues

- Fixed issue where large Control4 systems did not display properly, by creating a larger time-out window.
- Fixed issue with 3rd party devices reporting inaccurate SNMP information on OvrC by filtering LAG ports from the protocol.
- Improved handling of OvrC Pro local UI when HTTPS is enabled.
- Fixed issue where the OVRC-300-PRO physical factory default button did not work.
- Fixed issue with scheduler where relative time-zone was not taken into consideration.
- Fixed issue where device manufacturer's information would corrupt due to server outages.

Technical Support

For chat and telephone, visit **snp1.co/techsupport** • Email: **TechSupport@SnapOne.com**. Visit **snp1.co/tc** for discussions, instructional videos, news, and more.

Warranty and Legal Notices

Find details of the product's Limited Warranty at **snapone.com/legal/** or request a paper copy from Customer Service at **866.424.4489**. Find other legal resources, such as regulatory notices and patent and safety information, at **snapone.com/legal/**.

221213

OvrC