

# MS Series Switches Firmware V1.03.0 Release Notes

Released September 16, 2021

#### **Product SKUs Affected**

MS-1212	MS-2424
MS-2400	MS-4424
MS-2416	

#### **New User Interface Elements Added**

- Added IGMP Snooping Show Group Address
- Added SNMP Support
- Added SNTP Support
- Added Time Range Support
- Added Advance Logs Support
- Added Class of Service Support
- Added Loop Protection Support
- Added Diffserv (IPv4) Support
- Added Access Control Lists (MAC) Support
- Added Access Control Lists (IPv4) Support
- Added Access Control Lists (IPv6) Support
- Added Auto VoIP Support
- Added System Statistics Support

#### **Resolved Issues**

- Spelling errors in "Reset to Default" confirmation
- Control4 (C4) driver type showing as "Other"



## **MS Series Switches Firmware V1.01.0 Release Notes**

Released February 22, 2021

### **Product SKUs Affected**

MS-1212	MS-2424
MS-2400	MS-4424
MS-2416	

### **Added Features**

- Connections Added learned MAC address on port even if LLDP is not present
- PoE Added ability to set number of seconds to delay PoE On per port
- IGMP Snooping Added ability to disable automatic Multicast Router learning per port
- Added information icons (i) throughout the web interface to provide details instructions for each setting
- Driver updated MS switch to fully support Control4 driver

#### **Interfaces Section**

New sections added under Interfaces > Port

- Port Mirror
- Link Aggregation
- New option added under Interfaces > VLAN
- Added ability to configure VLAN Switchport mode as General

#### **Advanced Section**

New sections added under Advanced.

- Multicast Forwarding database
- LLDP
- LLDP-MED
- MAC Table
- ARP Table
- IP Routing (enable routing mode, configure IP interfaces)
- Router
- Tech-Support (output tech support debug logs)
- Utilities (ping, trace route, IP Conflict check)
- Management Access
- Class Of Service (Manage DSCP settings)

## **Resolved OvrC Cloud Issues and Features**

- Fixed OvrC Error When Saving Static IP Address
- PoE port now inactive active after being disabled and switch rebooted
- Fixed issue causing local web GUI to become inaccessible if no Internet access is present

#### Warranty and Legal Notices

Find details of the product's Limited Warranty at **snapone.com/legal/** or request a paper copy from Customer Service at **866.424.4489**. Find other legal resources, such as regulatory notices and patent and safety information, at **snapone.com/legal/**.

Copyright ©2021, Snap One, LLC. All rights reserved. Snap One its respective logos are registered trademarks or trademarks of Snap One, LLC (formerly known as Wirepath Home Systems, LLC), in the United States and/or other countries. 4Store, 4Sight, Control4, Control4 My Home, SnapAV, BakPak, OvrC, Pakedge, are also registered trademarks or trademarks of Snap One, LLC. Other names and brands may be claimed as the property of their respective owners. Snap One makes no claim that the information contained herein covers all installation scenarios and contingencies, or product use risks. Information within this specification subject to change without notice.

Version 210910

Part # DOC-00505

