



FIRMWARE UPDATE NOTES

RELEASE DETAILS

OvrC Pro App Version: 6.2.1.7

Release Date: 2021/06/03

Firmware Version:

- **OVRC-300-PRO Host Device Version:** 5.1.0.6
- **OVRC-100-HUB Host Device Version:** 5.1.0.6
- **AN-310-RT-4L2W Host Device Version:** 1.1.64
- **AN-110-RT-2L1W Host Device Version:** 1.0.86
- **AN-110-RT-2L1W-WIFI Host Device Version:** 1.0.86
- **RT-3100 Host Device Version:** 2.00.1.100626
- **RK-1 Host Device Version:** 2.00.1.100848
- **WR-1 Host Device Version:** 2.00.1
- **NK-1 Host Device Version:** 2.00.0.100267
- **EA Controllers Host Device Version:** 1.0.0.4
- **CA Controllers Host Device Version:** 1.0.0.4

ENHANCEMENTS

- Added Pakedge protocol to assist with migration of Pakedge devices to their respective firmware for OvrC-enablement.
- Improved handling of HTTPS on local UI of OvrC Pro devices.
- Improved Doorbird protocol from reporting non-Doorbird devices.
- Fixed issue with 3rd party devices falling offline on some customer sites in the field. For more details, see our [blog post](#).

KNOWN ISSUES

none.



FIRMWARE UPDATE NOTES

RELEASE DETAILS

OvrC Pro App Version: 6.2.0.5

Release Date: 2021/04/08

Firmware Version:

- **OVRC-300-PRO Host Device Version:** 5.1.0.2
- **OVRC-100-HUB Host Device Version:** 5.1.0.4
- **AN-310-RT Host Device Version:** 1.1.64
- **RT-3100 Host Device Version:** 2.00.1.100626
- **RK-1 Host Device Version:** 2.00.1.100848
- **NK-1 Host Device Version:** 2.00.0.100267

ENHANCEMENTS

- Added a secondary check for third party devices to increase accuracy of device connection status.
- Updated HTTPS SSL method from SSLv2.3 to TLSv1.2.
- Updated hostname as device name for Denon, Marantz, and Yamaha devices.
- Updated Device Discovery, Health Monitor, and Internet Test services to be disabled by default on newly deployed OvrC Pro devices.

RESOLVED ISSUES

- Fixed issue where large Control4 systems did not display properly, by creating a larger time-out window.
- Fixed issue with 3rd party devices reporting inaccurate SNMP information on OvrC by filtering LAG ports from the protocol.
- Improved handling of OvrC Pro local UI when HTTPS is enabled.
- Fixed issue where the OVRC-300-PRO physical factory default button did not work.
- Fixed issue with scheduler where relative time-zone was not taken into consideration.
- Fixed issue where device manufacturer's information would corrupt due to server outages.

KNOWN ISSUES

None.



FIRMWARE UPDATE NOTES

RELEASE DETAILS

Release Date: 2020/07/23

Firmware Version:

- **OVRC-300-PRO Host Device Version:** 5.1.0.2
- **OVRC-100-HUB Host Device Version:** 5.1.0.4
- **AN-110-RT Host Device Version:** N/A
- **AN-310-RT Host Device Version:** 1.0.64

NOTE: To get the latest hub application on the router or hub, please reboot after updating host device fw.

ENHANCEMENTS

- Added OvrC Pro Application version to device details page of Pro host device.
- Added protocol for Sony Bravia TVs (Android based models only Models ending in "D" or above).
- Updated the Denon/Marantz protocol with 2020 models with additional HDCP information.
- Updated the UI to display Samsung protocol information.
- Added Control4 protocol rework to match new UI/UX.
- Added HTTPS support for the local interface.

RESOLVED ISSUES

- Fixed slow response time in SSH and Telnet tools.
- Fix for Ubiquiti Unifi Switches changing default password.
- Fixed non-Doorbird devices from showing Doorbird protocol elements.
- Fixed firmware update timing issues wherein the device would sometimes error out and not boot.
- Fixed Binary switching bug wherein the switching was always off by one, causing mapping issues as well as the inability to select last inputs.
- Fixed the 12 hr scheduling option for speed-test.

KNOWN ISSUES

None.