



Pro App v7.3.0.1 and 7.3.0.2 Release Notes

Release Details

Release Date	2023/06/08
Firmware Version	7.3.0.1 and 7.3.0.2
Product SKUs Affected	X10 Routers (110, 110W, 310) OS 3.3.3+ for EA, CA, and CORE Controllers OvrC-300 and 100 Hubs ihiji APP-750 ihiji APP-2000 ihiji APP-2100 ihiji APP-2000-UK ihiji APP-2100-UK Pakedge WR-1 Pakedge WR-1-1 Pakedge NK-1 Pakedge RK-1 Pakedge RT-3100

Fixes

- Development support for future releases.

Pro App v7.3.0 Release Notes

Release Details

Release Date	2023/06/01
Firmware Version	7.3.0
Product SKUs Affected	X10 Routers (110, 110W, 310) OS 3.3.3+ for EA, CA, and CORE Controllers OvrC-300 and 100 Hubs ihiji APP-750 ihiji APP-2000 ihiji APP-2100 ihiji APP-2000-UK ihiji APP-2100-UK Pakedge WR-1 Pakedge WR-1-1 Pakedge NK-1 Pakedge RK-1 Pakedge RT-3100

Fixes

- Updated security.

Pro App v7.3.0 Release Notes

Release Details

Release Date	2023/05/18
Firmware Version	7.3.0
Product SKUs Affected	X10 Routers (110, 110W, 310) OS 3.3.3+ for EA, CA, and CORE Controllers OvrC-300 and 100 Hubs ihiji APP-750 ihiji APP-2000 ihiji APP-2100 ihiji APP-2000-UK ihiji APP-2100-UK Pakedge WR-1 Pakedge WR-1-1 Pakedge NK-1

Fixes

- Updated security.

Pro App v7.3.0 Release Notes

Release Details

Release Date	2023/05/04
Firmware Version	7.3.0
Product SKUs Affected	X10 Routers (110, 110W, 310) OS 3.3.3+ for EA, CA, and CORE Controllers OvrC-300 and 100 Hubs ihiji APP-750 ihiji APP-2000 ihiji APP-2100 ihiji APP-2000-UK ihiji APP-2100-UK

Fixes

- Updated security.

Pro App v7.3.0 Release Notes

Release Details

Release Date	2023/04/27
Firmware Version	7.3.0
Product SKUs Affected	X10 Routers (110, 110W, 310) OS 3.3.3+ for EA, CA, and CORE Controllers ihiji APP-750 ihiji APP-2000 ihiji APP-2100 ihiji APP-2000-UK ihiji APP-2100-UK

Fixes

- Updated security.

Pro App v7.3.0.0 Release Notes

Release Details

Release Date	2023/02/16
Firmware Version	7.3.0.0
Product SKUs Affected	X10 Routers (110, 110W, 310)

Fixes

- Updated security.

Pro App v7.2.0.6 Release Notes

Release Details

Release Date	2023/01/18
Firmware Version	7.2.0.6
Product SKUs Affected	EA Controllers CA Controllers CORE Controllers OvrC-300 and 100 Hubs X10 Routers (110, 110W, 310) Pakedge Routers (RK-1, WR-1, RT-3100) NK-1 NX-1 Invision App

Fixes

- Fixes an issue for possible negative values from cob_ping.

Pro App v7.2.0.5 Release Notes

Release Details

Release Date	2022/12/15
Firmware Version	7.2.0.5
Product SKUs Affected	Araknis x10 Series Routers Host Versions: 1.2.16 and 1.2.23

Fixes

- Fixes an issue with upgradability from firmware version 1.2.16 onwards.

Pro App v7.2.0 Release Notes

Release Details

Release Date	2022/11/17
Firmware Version	7.2.0
Product SKUs Affected	EA Controllers CA Controllers CORE Controllers OvrC-300 and 100 Hubs X10 Routers (110, 110W, 310) Pakedge Routers (RK-1, WR-1, RT-3100) NK-1 NX-1 Invision App

Fixes

- Fixed data storage location in Pakedge WR-1. Persistent data for OvrC Pro was not being properly stored.

Enhancements

- Added periodic service boundaries for an upcoming feature release
- Updated UI and device access for improved cybersecurity
- Modified SDDP client and server features to support multiple network interfaces
- Added SDDP listener for Araknis X20 routers
- Added additional logging data for changing environments, debugging discovered devices and for Control4 controllers

Pro App v7.1.0 Release Notes

Release Details

Release Date	2022/10/20
Firmware Version	7.1.0
Product SKUs Affected	EA Controllers CA Controllers CORE Controllers OvrC-300 and 100 Hubs X10 Routers (110, 110W, 310) Pakedge Routers (RK-1, WR-1, RT-3100) NK-1 NX-1 Invision App

Fixes

- Fix to accept x.x.x.254 addresses for static IP. Previously, this was not accepted by the OvrC Pro agent

Enhancements

- Support for 2022 Denon ([Learn More](#)) and Marantz AVR's ([Learn More](#)), pre-amps, and amplifiers
- Support for Sony projectors [Learn More](#)

Pro App v7.0 Release Notes

Release Details

Release Date	2022/09/22
Firmware Version	7.0
Product SKUs Affected	EA Controllers CA Controllers CORE Controllers OvrC-300 and 100 Hubs X10 Routers (110, 110W, 310) Pakedge Routers (RK-1, WR-1, RT-3100) NK-1 NX-1 Invision App

Fixes

- Minor bug fixes and cosmetic improvements

Enhancements

- Third-party integration with Sony AVRs, sound bars, and line array speakers. (See supported models)
- Services include adding the ability to turn zones on or off, mute zones, and perform firmware updates from OvrC
- For more information, see this Knowledge Base article:
<https://tech.control4.com/s/article/Improvements-made-to-OvrC-and-OvrC-Pro>
- Improved device discovery of Sony Bravia TVs that are wirelessly connected to the network

Pro App v6.4.0.9 Release Notes

Release Details

Release Date	2022/07/28
Firmware Version	6.4.0.9
Product SKUs Affected	EA Controllers CA Controllers CORE Controllers OvrC-300 and 100 Hubs X10 Routers (110, 110W, 310) NX-1 Invision App

Fixes

- Fixed an EA/CA controllers timing issue when booting the OvrC agent due to an incorrect reference MAC being pulled at boot.
- Fixed the CORE controller port duplex reading on the Ethernet port.
- Fixed the CORE controllers ST/SN reference on beta units that did not have the ST flashed to them.
- Fixed the controllers not showing online in OvrC due to incorrect interface binding.
- Fixed the CORE controllers method to WebConnect.

Enhancements

- Added OS version support on the Control4 controller running OS 3.2.2 or higher.
- Improved the connectivity of OvrC-enabled devices.
- Improved the SDDP discovery for 3rd party products.
- Improved the reliability of WebConnect when connecting to Araknis 110/310 routers.
- Improved the buffer and added efficient logging for Control4 mobile connections.

Pro App v6.4.0.3 Release Notes

Release Details

Release Date	2022/05/05
Firmware Version	6.4.0.3
Product SKUs Affected	EA Controllers CA Controllers


For all other OvrC Pro devices, [click here](#) to see their Pro App release notes.

Fixes

- Improved the timing of the Pro agent startup. This issue was identified where a Control4 controller showed a different MAC address in OvrC than what was on the device.

Enhancements

- Improved Control4 mobile app connection times.
- Controllers with multiple network interfaces (Ethernet and wireless) now appear as a single device. Both MAC addresses can be seen under the **Device Details**.



Pro App v6.3.0.6 Release Notes

Release Details

Release Date	2022/04/07
Firmware Version	6.3.0.6
Product SKUs Affected	OVRC-300-PRO Host Device Version: 5.1.0.6 OVRC-100-HUB Host Device Version: 5.1.0.8 AN-310-RT-4L2W Host Device Version: 1.1.66 AN-110-RT-2L1W Host Device Version: 1.0.88 AN-110-RT-2L1W-WIFI Host Device Version: 1.0.88 RT-3100 Host Device Version: 2.00.2.100632 RK-1 Host Device Version: 2.00.2.100853 WR-1 Host Device Version: 2.00.1.100321 NK-1 Host Device Version: 2.00.0.100267 Pakedge NX-1 Ihiji APP-750 Ihiji APP-2000 Ihiji APP-2100 Ihiji APP-2000-UK Ihiji APP-2100-UK

Enhancements

- Added ability for Pakedge devices to update the pro application without a reboot of the device.
- Updated the Hub Environment page to improve environment switching between dev/beta/prod.
- Fixed issue with webconnect wherein a user session would end quickly and abruptly due to cookie size limitations.

Pro App v6.3.0.4 Release Notes

Release Details

Release Date	2021/12/16
Firmware Version	6.3.0.4
Product SKUs Affected	OVRC-300-PRO Host Device Version: 5.1.0.6 OVRC-100-HUB Host Device Version: 5.1.0.8 AN-310-RT-4L2W Host Device Version: 1.1.66 AN-110-RT-2L1W Host Device Version: 1.0.88 AN-110-RT-2L1W-WIFI Host Device Version: 1.0.88 RT-3100 Host Device Version: 2.00.1.100626 RK-1 Host Device Version: 2.00.1.100848 WR-1 Host Device Version: 2.00.1 NK-1 Host Device Version: 2.00.0.100267 EA Controllers Host Device Version: 1.0.0.4 CA Controllers Host Device Version: 1.0.0.4

Enhancements

- Improved the accuracy of Control4 controller memory usage.
- Added VLAN configuration and scanning for locations where a Control4 controller is the OvrC Pro host.
- Allow for multiple attempts at updating Packedge APs that are running firmware v1.xx firmware.
- Allow for dynamic device port when using WebConnect via OvrC. No longer hard coded to 80.
- Added synchronization of the monitoring bell between the OvrC server and OvrC Pro host.
- Improved WebConnect for protocols that require SSL where a Control4 controller is the OvrC Pro host.
- Changed health monitor logic to not ping a device that ARPing found the wrong MAC address for.
- Increased worker thread count to help run faster scans on hardware that supports it.
- Added SNMP support for Access Networks/Ruckus switches and changed the logic to identify matching manufacturers.
- Added SDDP listener to non-Control4 OvrC Pro agents for improved device naming.
- Fixed timestamps on OvrC Pro hosts running on Control4 controllers.

Pro App v6.2.1.7 Release Notes

Release Details

Release Date	2021/06/03
Firmware Version	6.2.1.7
Product SKUs Affected	OVRC-300-PRO Host Device Version: 5.1.0.6 OVRC-100-HUB Host Device Version: 5.1.0.6 AN-310-RT-4L2W Host Device Version: 1.1.64 AN-110-RT-2L1W Host Device Version: 1.0.86 AN-110-RT-2L1W-WIFI Host Device Version: 1.0.86 RT-3100 Host Device Version: 2.00.1.100626 RK-1 Host Device Version: 2.00.1.100848 WR-1 Host Device Version: 2.00.1 NK-1 Host Device Version: 2.00.0.100267 EA Controllers Host Device Version: 1.0.0.4 CA Controllers Host Device Version: 1.0.0.4

Enhancements

- Added Pakedge protocol to assist with migration of Pakedge devices to their respective firmware for OvrC-enablement.
- Improved handling of HTTPS on local UI of OvrC Pro devices.
- Improved Doorbird protocol from reporting non-Doorbird devices.
- Fixed issue with 3rd party devices falling offline on some customer sites in the field. For more details, see our **blog post**.

Pro App v6.2.0.5 Release Notes

Release Details

Release Date	2021/04/08
Firmware Version	6.2.0.5
Product SKUs Affected	OVRC-300-PRO Host Device Version: 5.1.0.2 OVRC-100-HUB Host Device Version: 5.1.0.4 AN-310-RT-4L2W Host Device Version: 1.1.64 RT-3100 Host Device Version: 2.00.1.100626 RK-1 Host Device Version: 2.00.1.100848 NK-1 Host Device Version: 2.00.0.100267

Enhancements

- Added a secondary check for third party devices to increase accuracy of device connection status.
- Updated HTTPS SSL method from SSLv2.3 to TLSv1.2.
- Updated hostname as device name for Denon, Marantz, and Yamaha devices.
- Updated Device Discovery, Health Monitor, and Internet Test services to be disabled by default on newly deployed OvrC Pro devices.

Resolved Issues

- Fixed issue where large Control4 systems did not display properly, by creating a larger time-out window.
- Fixed issue with 3rd party devices reporting inaccurate SNMP information on OvrC by filtering LAG ports from the protocol.
- Improved handling of OvrC Pro local UI when HTTPS is enabled.
- Fixed issue where the OVRC-300-PRO physical factory default button did not work.
- Fixed issue with scheduler where relative time-zone was not taken into consideration.
- Fixed issue where device manufacturer's information would corrupt due to server outages.

Technical Support

For chat and telephone, visit snp1.co/techsupport • Email: TechSupport@SnapOne.com. Visit snp1.co/tc for discussions, instructional videos, news, and more.

Warranty and Legal Notices

Find details of the product's Limited Warranty at snapone.com/legal/ or request a paper copy from Customer Service at **866.424.4489**. Find other legal resources, such as regulatory notices and patent and safety information, at snapone.com/legal/.

Copyright ©2023, Snap One, LLC. All rights reserved. Snap One its respective logos are registered trademarks or trademarks of Snap One, LLC (formerly known as Wirepath Home Systems, LLC), in the United States and/or other countries. 4Store, 4Sight, Control4, Control4 My Home, SnapAV, Araknis Networks, BakPak, Binary, Dragonfly, Episode, Luma, Mockupancy, Nearus, NEEO, Optiview, OvrC, Pakedge, Sense, Strong, Strong Evolve, Strong VersaBox, SunBriteDS, SunBriteTV, Triad, Truvision, Visualint, WattBox, Wirepath, and Wirepath ONE are also registered trademarks or trademarks of Snap One, LLC. Other names and brands may be claimed as the property of their respective owners. Snap One makes no claim that the information contained herein covers all installation scenarios and contingencies, or product use risks. Information within this specification subject to change without notice. All specifications subject to change without notice.