



## OVRC PRO HUB FIRMWARE RELEASE NOTES

### RELEASE DETAILS

**Firmware Version:** 5.1.0.6

**Release Date:** 2021/06/03

**Affected SKUs:**

- OVRC-300-PRO
- OVRC-100-HUB

### ENHANCEMENTS

- Added debug tools for future sustainment.
- Updated codebase for compatibility with [OvrC Pro App 6.2.1.7](#).

### KNOWN ISSUES

none



## OVRC PRO HUB FIRMWARE RELEASE NOTES

### RELEASE DETAILS

**Release Date:** 2020/07/23

**Firmware Version:**

- **OVRC-300-PRO Host Device Version:** 5.1.0.2
- **OVRC-100-HUB Host Device Version:** 5.1.0.4

### ENHANCEMENTS

- Added OvrC Pro Application version to device details page of Pro host device.
- Added protocol for Sony Bravia TVs (Android based models only Models ending in "D" or above).
- Updated the Denon/Marantz protocol with 2020 models with additional HDCP information.
- Updated the UI to display Samsung protocol information.
- Added Control4 protocol rework to match new UI/UX.
- Added HTTPS support for the local interface.

### RESOLVED ISSUES

- Fixed slow response time in SSH and Telnet tools.
- Fix for Ubiquiti Unifi Switches changing default password.
- Fixed non-Doorbird devices from showing Doorbird protocol elements.
- Fixed firmware update timing issues wherein the device would sometimes error out and not boot.
- Fixed Binary switching bug wherein the switching was always off by one, causing mapping issues as well as the inability to select last inputs.
- Fixed the 12 hr scheduling option for speed-test.

### KNOWN ISSUES

None.